CONTENTS

Preface 3

Failure Mechanisms in Loess and the Effects of Moisture Content Changes on Remoulded Strength 5
E. DERBYSHIRE, T. A. DIJKSTRA, I. J. SMALLEY and Y. LI

Physico-Mechanical Properties of Loess in Poland (Studies *In Situ*) 17
Z. FRANKOWSKI

Engineering Geological Problems in Loess Regions of Hungary 25
P. FODOR and B. KLEB

A Landslide Type Occurring Frequently Along the Loess Bluff in the Hungarian Danube Section 31
M. PÉCSI

Changes in Loess Fabric Caused by Collapse: An Experimental Study 35
A. KLUKANOVA and J. SAJGALIK

Formation of Loess Fabric 41
J. SAJGALIK and A. KLUKANOVA

Loess Erosion on the Tokaj Big-Hill 47
A. KERÉNYI